

Oil Field Environmental Incident Summary

Incident: 20150909164242 **Date/Time of Notice:** 09/09/2015 16:42

Responsible Party: ENDURO OPERATING, LLC

Well Operator: ENDURO OPERATING, LLC

Well Name: BRONSON 1-26

Field Name: TEMPLE

Well File #: 10260

Date Incident: 9/5/2015

Time Incident: 04:00

Facility ID Number:

County: WILLIAMS

Twp: 159

Rng: 96

Sec: 26

Qtr:

Location Description:

Submitted By: Scott Hunsakor

Received By:

Contact Person: Scott Hunsakor
777 MAIN STREET
SUITE 800
FORT WORTH, TX 76102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	460	Barrels	460	Barrels	460	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 2/26/2016

Clean Up Concluded: 9/10/2015

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

Shut all wells pipelined into location, have tanker trucks empty dike and haul to disposal, place three sided tank on location and scrape soil inside dike, spread new gravel and inspect dike for damage

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 9/9/2015 **Status:** Reviewed - Assigned to Other Agency **Author:** O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a fire, remained within diking, according to the report. NDIC retains oversight. However, with the large volume reported to be released, the report has been forwarded to our NDDoH inspector for follow-up tomorrow.

Date: 9/10/2015 **Status:** Correspondence **Author:** O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received an email from Division inspector stating that the release appeared to have stayed on the well pad and on-site. No further followup at this time. NDIC retains oversight.

Date: 9/11/2015 **Status:** Inspection

Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On-site 09/09/2015 at 7:10 pm. Weather is 60 degrees F, sunny, light wind. Fire apparently destroyed tanks on-site. For the most part, all impact appears to stay on well pad. Some higher field electrical conductivity readings near entrance to the south but contaminants appear to have stayed on the well pad.